Appendix E

PAGE 02

CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD SAN DIEGO REGION

SANITARY SEWER OVERFLOW REPORT FORM

ALI	ITEMS ARE REQUIRED TO BE ADDRESSED					
1.	This report is (check one) Preliminary	⊠ Final	Revised Final	• •		
2.	Sanitary Sewer Overflow Sequential Tracking Number: 045011					
3.	Reported To: Fax - Brian Kelley (Enter Fax, Voice Mail, or Name of Regional Board Staff)					
4.	Date Reported: 01 / 11 / 05 (MM/DD/YY) Time Reported: 09 : 30 (Military or 24 Hour Time)					
5.	Reported By: John Burcham	: ·				
6.	Phone: (760)839 -6290	X .		•		
7.	Reporting Sewer Agency: <u>City of Escondido</u>					
8.	Responsible Sewer Agency: City of Escondido	· · · · ·				
9.	Overflow Start: Date: 01 / 11	/05	(MM/DD/YY)			
•	Time Reported: 09 ;	30	(Military or 24 Hour Time)			
	Overflow End: Date: 01 / 12	/05	(MM/DD/YY)	,		
	Time Reported: 17 : (00	(Military or 24 Hour Time)			
10.	Estimated Overflow Flow Rate: 200	<u>-</u>	(Gallons Per Minute)			
11.	Total Overflow Volume: 280,000		(Gallons)			
12.	Overflow Volume Recovered: 0		(Gallons)			
13.	Overflow Volume Released To Environment: 280,00	00	(Gallons)			
Sani	tary Sewer Overflow Location and Description:		: `.			
14.	Street and/or Address: 1521 S. Hale Ave.			-		
15.	City: Escondido		Zip Code: <u>92029</u>			
16.	County: SD	(SD, R	L, OR)			

17. Sanitary Sewer Overflow Structure ID:

	Treatment Flatt Equalization Pond					
18.	Number of overflows within 1,000 feet of this location in past 12 months: 0					
19.	. Dates of overflows within 1,000 feet of this location in past 12 months: ()				
20.		:				
	Roots Grease Line Break	Infiltration 🖂				
	Rocks Blockage Power Failure	Pump Station Failure				
	Debris Vandalism Flood Damage	Manhole Failure				
	Other 🛛 Unknown 🗌 Flood Damage 🔲	Private Property				
21.	Overflow Cause - Detailed Description of Cause:	· • —				
	Increased plant influent flows from rain. All available storage use at the Station 77 and San Elijo Treatment Plant. Pumping secondary effluent outfall line and strutures for catastrophic damage.	his site. City of San Diego Pum to creek to protect land and ocear				
		i				
22.	Sanitary Sewer Overflow Correction - Description of all preventative a planned:	and corrective measures taken or				
	Additional stroage capacity is in planning stages for treatment plant. system problems.	Looking at possible collection				
23.	Was there measurable precipitation during 72-hour period prior to the ove	rflow? Y 🛛 or N 🗍				
Initi	ial and Secondary Receiving Waters:					
24.	Did the conitant constant of	1				
25.	Did the sanitary sewer overflow reach surface waters other than a storm draim? Y or N					
26.	Name or description of initial receiving waters. (If none, type none) Escondido Creek					
27.						

P.04

Date: 01-13-05

Title: Resource Recovery Plant Superintendent

•